



There is USB HID Format issue will not be used, when the User used the Win10. You need change MSR driver to fix this issue, please follow step as below,


Step-1. Please open MSR Device's Properties from Device management and chose "Update Driver Software" button.




Step-2. Please chose "Browse my computer for driver software" button.



Step-3. Please chose "Let me pick from a list of devices on my computer" button.



Step-4. Please chose "HID-compliant driver" and press "Next" button.



Step-5. USB HID Format issue will be fixed.

